

FATAL CRASH REGISTER 2022

The following has been released in relation to a request for information relating to road safety audit outcomes.

Crash #	Crash Date	Location	Road Owner	Site inspection date	Recommendations
51504884	5-Jan-22	Midland Highway Brighton	State Growth	10-Jan-22	Nil
51508241	7-Jan-22	Agnes Street George Town	Council		Removed from road toll - medical episode
51519347	13-Jan-22	High St/Wellington St Longford	Council		Department is not responsible for Council road
51521751	16-Jan-22	Bass Highway Deloraine	State Growth	1-Feb-22	Nil
51588027	22-Feb-22	Osbourne Esplanade Kingston Beach	Council		Department is not responsible for Council road
51591016	24-Feb-22	Woolmers Lane Longford	Council		Department is not responsible for Council road
51597875	24-Feb-22	Brooker Highway Berriedale	State Growth	1-Mar-22	Arrange removal of the old tree stump which was impacted in the subject crash and two other tree stumps located nearby
51607389	8-Mar-22	Forth Road Don	Council		Department is not responsible for Council road
51611316	11-Mar-22	Seabrook Road Somerset	Council		Department is not responsible for Council road
51632465	25-Mar-22	Bass Highway Carrick	State Growth	29-Mar-22	Nil
51635844	30-Mar-22	Tasman Highway Goulds Country	State Growth	5-Apr-22	1. Remove overhanging branches from trees along the road reservation on the southern side of the road to improve visibility to the eastern W1-100 warning sign for western approach. 2. Replace the W8-2(45) Advisory Speed signs with W8-2(35) signs for both westbound and eastbound signs. 3. Increase the number of guideposts around the curves to comply with the Aust Standards. 4 Install chevron alignment marks (CAM's) D4-6B for westbound traffic. 5. The above works have been discussed and agreed upon with Network Manager responsible for this section of the road. The Network Manager will arrange for works to be undertaken.
51636194	30-Mar-22	Bass Hwy/Oldinaroad Wynyard	State Growth	8-Apr-22	Close the Wilkinson Street junction with the Bass Highway
51641403	4-Apr-22	Westella Drive Ulverstone	Council		Department is not responsible for Council road
51644655	7-Apr-22	Osprey Road Claremont	Council		Department is not responsible for Council road
51646617	10-Apr-22	Cecilia Street St Helens	State Growth	17-May-22	Nil
51649924	14-Apr-22	Bathurst St/HomePoint Parad/Lower Charles St Launceston	State Growth	16-May-22	Nil

LEGEND

		Completed until Coroners report is received.
		Coroners report received.
		Medical episode removed from road toll.
		No report received yet or action has not been completed.
		Council Road - Dept not responsible - no further action

FATAL CRASH REGISTER 2022

51650529	18-Apr-22	Futuna Ave Park Grove Burnie	Council		Department is not responsible for Council road
51651813	21-Apr-22	North Road Reekara King Island	State Growth	11-May-22	Nil
51652365	22-Apr-22	Scenic Hill Road Huonville	Council		Department is not responsible for Council road
51659095	30-Apr-22	Brinktop Road Penna	Council		Department is not responsible for Council road
51663314	5-May-22	Main Road, Berridale, Glenorchy	Council		Department is not responsible for Council road
51663278	5-May-22	West Tamar Highway/Bridgenorth Road Legana	State Growth	16-May-22	Nil
51664781	6-May-22	Lake Leake Road Campbell Town	State Growth	10-May-22	Nil
51667149	9-May-22	Mill Road Wesley Vale Latrobe	Council		Department is not responsible for Council road
51668647	10-May-22	Brinktop Road Penna	Council		Department is not responsible for Council road
51677776	20-May-22	Wentworth street Newstead	Council		Department is not responsible for Council road
51679713	23-May-22	Good Shepherd Circle Sandy Bay	Council		Department is not responsible for Council road
51702478	14-Jun-22	Bass Highway Latrobe	State Growth	17-Jun-22	Nil
51708336	20-Jun-22	Greens Beach road	Council		Department is not responsible for Council road
51717208	1-Jul-22	East Tamar Highway/University Way Newnham	State Growth	5-Jul-22	Nil
51719693	6-Jul-22	Lewisham Road Forcett	Council		Removed from road toll - medical episode
51721791	10-Jul-22	Huon Road Longley	Council		Department is not responsible for Council road
51724860	14-Jul-22	Dampier Street and Schouten Street Warrane	Council		Department is not responsible for Council road
51727553	20-Jul-22	Arthur Highway, Sorell (2 km south of Sorell)	State Growth		Removed from road toll - medical episode
51730531	27-Jul-22	Midland Highway South Launceston	State Growth	1-Aug-22	Nil
51754337	27-Aug-22	South Arm Road Sandford	State Growth	1-Sep-22	Install Winding Road signage on both approaches to the series of curves – refer attached signage plan. And Install CAM signage for northbound traffic – refer attached signage plan
51755483	29-Aug-22	Lilydale Road Rocherlea	State Growth	31-Aug-22	Nil

FATAL CRASH REGISTER 2022

51758500	4-Sep-22	Tasman Highway Tonganah	State Growth	13-Sep-22	Nil
51757662	2-Sep-22	Evandale Road / Hobart Road	State Growth	20-Sep-22	1. Replaced faded W2-7 roundabout ahead with new W2-7(B) sign. 2. Replace damaged and missing D4-1-1 unidirectional hazard Marker. 3. Install new R1-3 (B) roundabout give way signs on the lefthand sides for southbound, westbound and northbound approaches at the roundabout. 4. Reinstate the central street lighting. 5. Some of the above actions affecting the Council section of Hobart Road were discussed and agreed to onsite with the Northern Midland Council's Engineering officer
51766961	16-Sep-22	East Tamar Highway Dilston	State Growth	26-Sep-22	Nil
51781849	8-Oct-22	Inglewood Road Andover	Council		Department is not responsible for Council road
51791920	14-Oct-22	Midland Highway Oatlands	State Growth		Nil
51799717	22-Oct-22	Bass Highway Latrobe	State Growth	27-Mar-23	Nil
51802875	26-Oct-22	Midland Highway Granton	State Growth	2-Nov-22	Nil
51808216	5-Nov-22	Tram Road Oldina	Council		Department is not responsible for Council road
518130041	15-Nov-22	Semmens Road St Marys	Council		Department is not responsible for Council road
51817470	25-Nov-22	Tasman Highway Runnymede	State Growth	30-Nov-22	Remove the impacted strand of trees
51818900	28-Nov-22	Main Street Huonville	State Growth	6-Dec-22	Advise the service station owner the pylon sign may restrict sight distance to a pedestrian approaching the access from the south and the accesses are not clearly defined and advise Huon Valley Council the footpath/accesses are not clearly defined along the frontage of 58-60 Main street
51844628	17-Dec-22	Tasman Highway Orford	State Growth	2-Feb-23	Delineate the culvert by installing guide posts either side and replace missing RRPM's when maintenance activities allow